



## TRACK RECORD

AquaTerra and our in-house trained technicians have been successfully engineering and installing QuikDeck® internationally since 2016. Below is a list of our completed project to date.

| CLIENT         | ASSET      | PROJECT DESCRIPTION  | AREA               | DATE      |
|----------------|------------|--|--------------------|-----------|
| Marathon Oil   | Brae Alpha | Access to the underside of lifeboats / platform structure to carry out fabric maintenance. | 200m <sup>2</sup>  | 2016      |
| Fairfield      | Dunlin     | Removal of cutting chute   | 45m <sup>2</sup>   | 2017      |
| Fairfield      | Dunlin     | Underdeck steelwork replacement (NE D Deck)  | 24m <sup>2</sup>   | 2017      |
| Fairfield      | Dunlin     | Conductor Removal using QuikDeck   | 1200m <sup>2</sup> | 2018 - 21 |
| Fairfield      | Dunlin     | D Deck QuikDeck for Steelwork Replacement  | 60m <sup>2</sup>   | 2018      |
| Chrysaor       | Armada     | Underdeck access for PFP repairs   | 468m <sup>2</sup>  | 2018      |
| Marathon Oil   | East Brae  | Caisson replacement  | 40m <sup>2</sup>   | 2018      |
| Brand Venko    | Clipper    | Bridge link repairs  | 375m <sup>2</sup>  | 2018      |
| Marathon Oil   | Brae Alpha | Walkway steelwork replacement / FM   | 360m <sup>2</sup>  | 2018      |
| Aker           | Mariner    | Outboard Maintenance   | 40m <sup>2</sup>   | 2018 - 20 |
| Rock Rose      | East Brae  | Caisson removal & replacement  | 50m <sup>2</sup>   | 2019      |
| ConocoPhillips | Britannia  | HAOD pipe replacement  | 200m <sup>2</sup>  | 2019      |
| Rock Rose      | Brae Bravo | Riser Removal  | 85m <sup>2</sup>   | 2019 - 20 |
| Fairfield      | Dunlin     | Concrete leg clearance D   | 50m <sup>2</sup>   | 2019 - 20 |
| Total          | Dunbar     | PFP Repairs  | 120m <sup>2</sup>  | 2019      |
| BP             | Andrew     | Riser / pipework FM & Inspection   | 100m <sup>2</sup>  | 2019      |
| ConocoPhillips | Judy       | Primary / Secondary Steelwork Installation   | 215m <sup>2</sup>  | 2019      |
| BP             | Andrew     | Riser / pipework FM & Inspection   | 100m <sup>2</sup>  | 2020      |
| Fairfield      | Dunlin     | Concrete leg clearance A/B/C/D   | 50m <sup>2</sup>   | 2020 - 21 |
| Total          | Dunbar     | Jacket Repairs   | 70m <sup>2</sup>   | 2020      |
| Worley/CNOOC   | Scott      | 10te Runway beam recertification   | 30m <sup>2</sup>   | 2021      |
| Worley/CNOOC   | Scott      | Casson replacement   | 85m <sup>2</sup>   | 2021      |
| TAQA           | East Brae  | Casson replacement   | 50m <sup>2</sup>   | 2021      |